



City of Leavenworth

100 N. 5th St.
Leavenworth, KS 66048
(913)684-0378

Building Permit

Application Number	14873
Date	02/02/2024
Permit Type	LAND DISTURBANCE ONE SF

PARCEL NUMBER	STREET ADDRESS
0773603037001010	513 MAPLE STREET

ZONE CODE	JURISDICTION
R16	LEAVENWORTH

OWNER INFORMATION		APPLICANT INFORMATION	
NAME:	YOUNG-HENDERSON, BRITTAN & ALLEN, EDWARD	NAME:	BRYANT CONSTRUCTION
ADDRESS:	320 VINE ST LEAVENWORTH, KS 66048	ADDRESS:	15280 BIRAR ROAD
PHONE:		PHONE:	913-724-4100

CONTRACTOR INFORMATION			
NAME:	BRYANT CONSTRUCTION	LICENSE NUMBER:	
ADDRESS:	15280 BIRAR ROAD	LICENSE EXP. DATE:	
PHONE:		INSURANCE EXP. DATE:	

BUILDING INFORMATION	
PROPOSED USE:	HEATED SQ. FT:
CONSTRUCTION TYPE:	UNHEATED SQ. FT:
NUMBER OF STORIES:	GARAGE SQ. FT:
ESTIMATED COST OF CONSTRUCTION:	NUMBER OF STORIES

PROJECT DESCRIPTION	SCOPE OF WORK
LAND DISTURBANCE ONE SF	CONSTRUCT A NEW 3 BEDROOM 2 BATHROOM SINGLE FAMILY DWELLING

PERMIT DETAILS:

I, the undersigned, hereby agree to comply with all applicable laws regulating the work. I have also received a copy of this document and understand that it is my responsibility to inform this office of any change of contractor by completing and submitting a change of contractor form if necessary. Separate permits are required for electrical, plumbing, heating, ventilating or air conditioning. It is the responsibility of the owner/applicant to identify and abide by all easements, covenants and other regulations related to land use that may be affected by the construction work for which this permit is issued.

ANY PERMIT ISSUED EXPIRES 180 DAYS AFTER ISSUANCE IF NO WORK HAS COMMENCED.
ANY PERMIT ISSUED SHALL EXPIRE 180 DAYS AFTER ISSUANCE IF THE WORK IS DISCONTINUED FOR 180 DAYS.

Signature of Owner/Contractor


Signature of Approving Official

ORIGINAL COPY

Permit Number	16647
Total Fees	

Project Inspection Log

Address: 513 MAPLE STREET
 Project: NSFD
 App # 14873
 Permit # 16647
 Issued Date: 02/02/2024

Owner Name: ALLEN YOUNG-HENDERSON

Contractor Name: BRYANT CONSTRUCTION

YEAR : 20²⁴

Day	January	February	March	April	May	June	July	August	September	October	November	December
1												
2							MF					
3												
4						MF						
5											MF	
6												
7			MEC									
8					MF					MF		
9				MF								MF
10									MF			
11												
12												
13								MF				
14												
15					MF		MF					
16												
17												
18						MF					MF	
19												
20												
21												
22										MF		
23				MF								MF
24									MF			
25												
26												
27								ME				
28			MEF									
29					MF		MF					
30												
31							1					

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple		LDP# 14873
Weather: 50°F	Pollution Control Measures (BMP) Checklist:	
Rain in last 24 hrs (inches): < 1/2"	<input type="checkbox"/> Inlet Barrier (i.e.: gravel bags)	
Owner / Permittee: Henderson	<input type="checkbox"/> Sediment Barriers (i.e.: ditch checks)	
A. Current Construction / Active Areas: New SFR	<input type="checkbox"/> Erosion Blankets, Hydromulch / Seed, etc	
	<input checked="" type="checkbox"/> Stabilized Construction Entrance	
	<input type="checkbox"/> Stream Crossings	
	<input checked="" type="checkbox"/> Seed / Sod Areas	
	<input type="checkbox"/> Sediment Basins & Discharge Locations	
	<input type="checkbox"/> Borrow Areas	
	<input checked="" type="checkbox"/> General Site Condition (trash, etc)	

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

Seeded - Waiting For Growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

1/21/25
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 10° F

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

Sealed - Waiting For Growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

1/7/25
Date of Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 46° F

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

Seeded - Waiting for Growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

12/23/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: SR Maple

LDP# 14873

Weather: 45°F

Pollution Control Measures (BMP) Checklist:

Rain in last 24 hrs (inches): < 1/2"

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

Seeded - Waiting For Growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

12/9/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
- Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 40° F Clear

Pollution Control Measures (BMP) Checklist:

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

A. Current Construction / Active Areas:

New STR

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.


Seeded - Waiting for Growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

11/18/24

Date of
Inspection



Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
 • Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 55° F

Pollution Control Measures (BMP) Checklist:

Rain in last 24 hrs (inches): < 1/2"

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New 3FR

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

Sealed - waiting for growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

11/5/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
- Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 80° F

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

Seeded - Waiting For Growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

10/22/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple **LDP#** 14873

Weather: 70° F

Pollution Control Measures (BMP) Checklist:

Rain in last 24 hrs (inches): < 1/2"

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

Sealed - waiting for growth

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

10/8/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 80°F Clear

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

Project Complete - lot Sealed -

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

9/24/24
Date of Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
- Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP#

Weather: 80°F Clear

Pollution Control Measures (BMP) Checklist:

Rain in last 24 hrs (inches): < 1/2"

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New STR

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

9/10/24


Date of Inspection



Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
- Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly • Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Inspector Signature


Date of Inspection
 9/27/24

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours unless otherwise noted. All other BMP's on site are considered to be in good working condition.

Erosion and Sediment Control Inspection Report Form	
Project Name and Location: 513 Maple LDP# 14873	
Weather: 90°F Clear Rain in last 24 hrs (inches): $\frac{1}{2}$	
Owner / Permittee: Henderson	
A. Current Construction / Active Areas:	
New SFR	
<input checked="" type="checkbox"/> Inlet Barrier (i.e.: gravel bags)	B. Problem Areas / Special Observations (*Note problem areas ONLY below*):
<input checked="" type="checkbox"/> Sediment Barriers (i.e.: ditch checks)	
<input checked="" type="checkbox"/> Erosion Blankets, Hydromulch / Seed, etc	
<input checked="" type="checkbox"/> Stabilized Construction Entrance	
<input checked="" type="checkbox"/> Stream Crossings	
<input type="checkbox"/> Seed / Sod Areas	
<input type="checkbox"/> Sediment Basins & Discharge Locations	
<input type="checkbox"/> Borrow Areas	
<input checked="" type="checkbox"/> General Site Condition (trash, etc)	
Pollution Control Measures (BMP) Checklist:	
BMP Location Observations, Effectiveness, & Corrective Actions Ordered	C. Listing of Areas where construction operations have permanently or temporarily stopped, stabilization measures initiated.
D. Have items noted on last inspection been corrected? Yes No (If No, Explain):	

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple		LDP# 14873
Weather: 70° Cloudy	Pollution Control Measures (BMP) Checklist: <input checked="" type="checkbox"/> Inlet Barrier (i.e.: gravel bags) <input checked="" type="checkbox"/> Sediment Barriers (i.e.: ditch checks) <input type="checkbox"/> Erosion Blankets, Hydromulch / Seed, etc <input checked="" type="checkbox"/> Stabilized Construction Entrance <input checked="" type="checkbox"/> Stream Crossings <input type="checkbox"/> Seed / Sod Areas <input type="checkbox"/> Sediment Basins & Discharge Locations <input type="checkbox"/> Borrow Areas <input checked="" type="checkbox"/> General Site Condition (trash, etc)	
Rain in last 24 hrs (inches): < 1/2"		
Owner / Permittee: Henderson		
A. Current Construction / Active Areas: New SFR		

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

8/13/24
 Date of
 Inspection


 Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
 • Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 95° F Clear

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

7/29/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple		LDP# 14873
Weather: 90° F Clear		Pollution Control Measures (BMP) Checklist: <input checked="" type="checkbox"/> Inlet Barrier (i.e.: gravel bags) <input checked="" type="checkbox"/> Sediment Barriers (i.e.: ditch checks) <input type="checkbox"/> Erosion Blankets, Hydromulch / Seed, etc <input checked="" type="checkbox"/> Stabilized Construction Entrance <input checked="" type="checkbox"/> Stream Crossings <input type="checkbox"/> Seed / Sod Areas <input type="checkbox"/> Sediment Basins & Discharge Locations <input type="checkbox"/> Borrow Areas <input checked="" type="checkbox"/> General Site Condition (trash, etc)
Rain in last 24 hrs (inches): < 1/2"		
Owner / Permittee: Henderson		
A. Current Construction / Active Areas: New SFR		

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

7/15/24
Date of Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
 • Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple		LDP# 14873
Weather: 90°F Clear	Pollution Control Measures (BMP) Checklist:	
Rain in last 24 hrs (inches): < 1/2"	<input checked="" type="checkbox"/> Inlet Barrier (i.e.: gravel bags)	
Owner / Permittee: Henderson	<input checked="" type="checkbox"/> Sediment Barriers (i.e.: ditch checks)	
A. Current Construction / Active Areas: New SFR	<input checked="" type="checkbox"/> Erosion Blankets, Hydromulch / Seed, etc	
	<input checked="" type="checkbox"/> Stabilized Construction Entrance	
	<input checked="" type="checkbox"/> Stream Crossings	
	<input type="checkbox"/> Seed / Sod Areas	
	<input type="checkbox"/> Sediment Basins & Discharge Locations	
	<input type="checkbox"/> Borrow Areas	
	<input checked="" type="checkbox"/> General Site Condition (trash, etc)	

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

7/2/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 84° F Clear

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

6/18/24
Date of Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple		LDP# 14873
Weather: 75° F Clear	Pollution Control Measures (BMP) Checklist:	
Rain in last 24 hrs (inches): < 1/2"	<input checked="" type="checkbox"/> Inlet Barrier (i.e.: gravel bags)	
Owner / Permittee: Henderson	<input checked="" type="checkbox"/> Sediment Barriers (i.e.: ditch checks)	
A. Current Construction / Active Areas: New SPR	<input checked="" type="checkbox"/> Erosion Blankets, Hydromulch / Seed, etc	
	<input checked="" type="checkbox"/> Stabilized Construction Entrance	
	<input checked="" type="checkbox"/> Stream Crossings	
	<input type="checkbox"/> Seed / Sod Areas	
	<input type="checkbox"/> Sediment Basins & Discharge Locations	
	<input type="checkbox"/> Borrow Areas	
	<input checked="" type="checkbox"/> General Site Condition (trash, etc)	

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

6/4/24
Date of Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 72° F

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

5/21/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 70°F Clear

Pollution Control Measures (BMP) Checklist:

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Bryant Const

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

A. Current Construction / Active Areas:

New SFR

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

5/8/24

Date of Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
 • Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 68°F Clear

Pollution Control Measures (BMP) Checklist:

Rain in last 24 hrs (inches): < 1/2"

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped: stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

4/23/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: 60° F Clear

Rain in last 24 hrs (inches): < 1/2"

Owner / Permittee: Henderson

A. Current Construction / Active Areas:

New SFR

Pollution Control Measures (BMP) Checklist:

- Inlet Barrier (i.e.: gravel bags)
- Sediment Barriers (i.e.: ditch checks)
- Erosion Blankets, Hydromulch / Seed, etc
- Stabilized Construction Entrance
- Stream Crossings
- Seed / Sod Areas
- Sediment Basins & Discharge Locations
- Borrow Areas
- General Site Condition (trash, etc)

B. Problem Areas / Special Observations(*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered


C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

4/9/24

Date of
Inspection



Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
 • Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple		LDP# 14873
Weather: 50° F Clear	<u>Pollution Control Measures (BMP) Checklist:</u> <input type="checkbox"/> Inlet Barrier (i.e.: gravel bags) <input checked="" type="checkbox"/> Sediment Barriers (i.e.: ditch checks) <input type="checkbox"/> Erosion Blankets, Hydromulch / Seed, etc <input checked="" type="checkbox"/> Stabilized Construction Entrance <input type="checkbox"/> Stream Crossings <input type="checkbox"/> Seed / Sod Areas <input type="checkbox"/> Sediment Basins & Discharge Locations <input type="checkbox"/> Borrow Areas <input checked="" type="checkbox"/> General Site Condition (trash, etc)	
Rain in last 24 hrs (inches): < 1/2"		
Owner / Permittee: Bryant Construction		
<u>A. Current Construction / Active Areas:</u> New SFR		

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):

BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain:)

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

3/28/24
Date of Inspection

Michael J. Follmer
Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
 • Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix

Erosion and Sediment Control Inspection Report Form

Project Name and Location: 513 Maple

LDP# 14873

Weather: Cloudy 50° F

Rain in last 24 hrs (inches): 0

Owner / Permittee: Bryant Const

A. Current Construction / Active Areas:

New House
Entire Lot

Pollution Control Measures (BMP) Checklist:

- ~~NA~~ Inlet Barrier (i.e.: gravel bags)
- OK Sediment Barriers (i.e.: ditch checks)
- NA Erosion Blankets, Hydromulch / Seed, etc
- ~~NA~~ Stabilized Construction Entrance **OK**
- NA Stream Crossings
- NA Seed / Sod Areas
- NA Sediment Basins & Discharge Locations
- NA Borrow Areas
- OK General Site Condition (trash, etc)

B. Problem Areas / Special Observations (*Note problem areas ONLY below*):


BMP	Location	Observations, Effectiveness, & Corrective Actions Ordered

C. Listing of Areas where construction operations have permanently or temporarily stopped; stabilization measures initiated.

D. Have items noted on last inspection been corrected? Yes No (if No, Explain):

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 24 hours, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

3/7/24
Date of
Inspection


Inspector Signature

- 6 Goals • No Sediment Leaves the Site • Lines of Defense Everywhere & Always • Cover Quickly
• Protect the Swale, Ditch, and Channel • Keep Clean Water Clean • Inspect, Clean & Fix